



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 8.10Z
09/19/2011

**Updates from previous versions:
Bug Fixes:**

1. Changed the Site Info Grid so that when clicking on a Magnum row the respective tab of the selected Magnum will be highlighted.
2. Fixed buttons on button bar from being enabled and disabled incorrectly from various functions. Audited the desired functionality of each button and enabled or disabled it according to a single function, instead of multiple as before.
3. Fixed bug causing MCS-Connect to crash when disconnecting with the "Disconnect" button from a Remote Ethernet connection. MCS-Connect was causing an error and not closing the Information UI when opening the Main UI.
4. Completed the bug fix made in 8.10X for the "Control On" field, it was incomplete and caused the same bug seen prior to 8.10X. The status screen was loading incorrectly and was displayed all over the Information UI.
5. CENT software only: Changed 3rd Column in Circuit State Table from "PSI DIFF" to "OIL DIFF"
6. REFR software only: Fixed bug that caused an exception in the User Defined Control Interface that caused all fields to display blank.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.