



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 9.03S
09/26/2012

Updates from previous versions:

New Features:

1. Adding the mouse listener for the inactivity timeout shutdown to more areas of the info grid.
2. Adding DEW PT sensor type (#19), 1 Decimal place, characters (d,d,d).

Bug Fixes:

1. Changed header in chiller circuit states.
2. Extended ID using incorrect value with new SW using older config.
3. Removed "Johnson N2" from the Protocol combo box in the Service Panel.
4. In Micro Mag when filling in the Mod Gas grid the Ignition temp column is getting the wrong print character. Resolution - I changed how the column gets the character.
5. SI value popup created when user changes an SI to Manual is saving the new value incorrectly. Resolution - Changed temporary variable used to store new value. Also, centered the popup in viewable window.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.