



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.00D
06/12/2013

Updates from previous versions:

Bug Fixes:

1. The alarm lockout popup is displaying incorrect values and headers for the new RO columns. When getting the index of the first RO MCS-Connect was subtracting from the RO index instead of the circuit index. **RESOLUTION** - Subtracting from the correct index to get the correct RO names and values for the new columns.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.