



SOFTWARE RELEASE NOTES

MCS-CONNECT

Version 14.01L

04/02/2014

Updates from previous versions:

Bug Fixes:

1. The Graphics lock feature is not working correctly. This is caused by the changes made for the new XML based graphics package. When checking the graphics file name extension before it had been loaded from the Magnum. RESOLUTION - Made sure that the system graphic filename had been initialized before checking its value to determine the graphics type.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2014. Copying or distributing this document is prohibited unless expressly approved by MCS.