



# SOFTWARE RELEASE NOTES

MCS-CONNECT  
Version 18.05.09  
10/14/2016

## Updates from previous versions:

### New Features:

1. Added checks to the test for EXVs and LLSs to include the new HCRF firmware.
2. Added support for EXVs in REF and HCRF firmware. Moved 4 columns from the Circuit Grid to the EXV grid.
3. Added code to delete files created by Diagnostic save and Alarm alerts after zipping them.
4. Added new states for REF and HCRF firmware.

### Bug Fixes:

1. Changed the test for the Control On value in RTU Firmware to match the change in the SW. Heating is using different fields now.
2. The PT chart for the new R421a refrigerant is incorrect. RESOLUTION - Changed Array to match the PT chart.
3. Previous change was not backwards compatible with older Firmware RESOLUTION - Added a test for Firmware pre 17.23 and coded it the old way.
4. The REF and HCRF config types were not displaying the COMP start times and % in the FLA popup. RESOLUTION - Added a check that included these types.

Any questions regarding this release, contact:  
[support@mcscontrols.com](mailto:support@mcscontrols.com)

---

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905  
(239)694-0089 FAX: (239)694-0031 [www.mcscontrols.com](http://www.mcscontrols.com)

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2016. Copying or distributing this document is prohibited unless expressly approved by MCS.