SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.00L
07/22/2013

Updates from previous versions:
New Features:

1.   New AO Type "2-10 Volt" added to V14 cfgs.

Bug Fixes:

1.   Loss of communication when transmitting a config to the Magnum or at the least taking an extended amount of time. After troubleshooting I noticed that the Magnum is missing bytes occasionally causing MCS-Connect to resend messages. RESOLUTION - I added a 1/2 second delay between some messages when transmitting to allow the Magnum time to process the large messages.
2.   The Print to file function was locking up MCS-Connect not allowing the user to do anything but shut it down if the file chooser was closed or canceled. RESOLUTION - Added an else case for when the file chooser returns null that restarts the refresh, fixes the cursor and un-hides the button bar.