SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 17.00D
11/06/2014

Updates from previous versions:
Bug Fixes:

1. When adjusting the Manual Status of AOs for V17 the index is incorrect. This is caused by lack of a check for this cfg type in the editor. RESOLUTION - Added v17 to the config type check.

2. The info grids were not being painted properly when first initializing the status grids. This was caused by adding the desktop Panel to the info Tabbed Pane before all internal Frames had been added and initialized. RESOLUTION - I moved the code to add the desktop to the Info Tabbed Pane to a spot after all internal frames have been initialized making the transition much cleaner.

3. In the Lookup Table Editing Frame any changes made to the table do not persist until the edited cell loses focus. RESOLUTION - I added code to the "send changes" button listener to fire the table's lost Focus listener when it is clicked.