SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 17.00O
2/13/2015

Updates from previous versions:
Bug Fixes:

1. Testing EXV for MicroMag code exposed some bugs that needed to be fixed.
2. The SI Manual Status Editor was not working for MicroMag. This was caused by the creation of a specific version of SI Eerom instead of a version based on device type. RESOLUTION - Replaced code with Device specific Eerom.
3. In the MicroMags setpoint grid the min and max adjust columns need to be shown with and adjusted by a one decimal float instead of an integer.
4. The SI Manual Status Editors value popup was being hidden behind the Info UI and causing users to have to restart MCS-Connect before they could set any more SIs to Manual. RESOLUTION - Forced the popup to always be on top of any other UI.
5. Combined 2 nested if statements to form 1 dual condition if statement due to the first test passing and causing graphics to not update.