



SOFTWARE RELEASE NOTES

MCS-CONNECT **Version 17.00L** **01/15/2015**

Updates from previous versions:

New Features:

1. REFR Alarm Lockout History Added to function that creates Lockout history popup.

Bug Fixes:

1. In Modbus V13 made a formatting change to decimal in the Bitmask column, set the limits on the # of Registers column to 1 or 2, showing all specials in the specials combo box for each function type and fixed some bugs when receiving a cfg.
2. In the Pump Group Grid's Rate of Change column there was no decimal place being used. RESOLUTION - Added code to use the Control on fields decimal place value.
3. Added checks for V17 Config types into Graphic HTML Loader class.
4. HTML graphics stopped working. This was due to the lack of a 32 bit swt.jar library that was removed. RESOLUTION - Added swt.jar Library back that was removed.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.