



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 17.11.04
2/24/2016

Updates from previous versions:

New Features:

1. Added a new Sensor Type #168 VIRTUAL_VANE_INDICATOR
2. Added a new Alarm type to match Firmware. #483 "Vane CLS/OPN FLT"

Bug Fixes:

1. REFR circuit state headers were incorrect. RESOLUTION - Changed field used to index into header array to correct field.
2. Removed a call to Refresh one specific Setpoint memory location when in Graphics as it was causing delays to the screen refresh. Will revisit this and determine the cause to find a better solution.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2016. Copying or distributing this document is prohibited unless expressly approved by MCS.