



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 18.04.07
9/7/2016

Updates from previous versions:

New Features:

1. Added HCRF config type to match REF cfg type.

Bug Fixes:

1. The Live Graph feature was not working with the MicroMag. Resolution: Created separate functions for the MicroMag to use that matched its structures.
2. Adjusted the numerical validation in the Live Graphs X-axis setup test box due to it invalidating all zeros.
3. The FLA popup when clicking on an RO was displaying too much information. Resolution: Reinitialized the flag that was incorrectly keeping everything as having a starting Comp Percentage.
4. In Refrig Ram V14 a test for size was looking at \geq instead of just $>$ Resolution: Changed to $>$
5. The path to the Graph folder was hardcoded for the Windows path when saving a Live Graph causing it to not save files on the touchscreen. Resolution: Used the paths variable to set the path based on OS.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2016. Copying or distributing this document is prohibited unless expressly approved by MCS.