



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 9.20A
01/24/2013

Updates from previous versions:

New Features:

1. Due to the instability displayed lately and its lack of support, the JDIC library used to embed a browser into MCS-Connect has been replaced with the Native Swing library developed by The DJ Project. The Native Swing library allows an easy integration of some native components into Swing applications, and provides some native utilities to enhance Swing's APIs. The Native Swing Library contains a rich web browser component that should improve the graphics performance. Removed all JDIC components and its library from this project. This change allowed me to remove some of the recent time delay code implemented to improve the stability of MCS-Connect using the JDIC. Hence the improvement in speed.

Bug Fixes:

1. When changing the SI Type the verification popup was being called multiple times if the user changed the sensor type more than once per session. This was causing the verification popup to remain even after the user verified that the change was to be made. RESOLUTION - I added code to check if a popup was currently present before creating another one.
2. Changing the font size of the Info Tabbed Pane and the Info Table based on resolution of user.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.