



# SOFTWARE RELEASE NOTES

MCS-CONNECT  
Version 17.09.00  
12/4/2015

## Updates from previous versions:

### New Features:

1. Added a check for CENT Firmware to the check for EXVs and LLS in V17 & V14.
2. Added Purge values to the XML Graphic Builder so they can be displayed in the Graphics.
3. Adding tag to XML to allow the hiding of buttons based on Authorization level.
4. Adding image tag into the input tags for xml graphics.
5. Added a keypad to all RO FLA popups.

### Bug Fixes:

1. Removing Secondary XML file for multi-mag communication, all secondary tags will now be in primary XML file.
2. Modbus Write AO type is assuming 1 decimal like other AOs when changing the Manual value. Changed it to use the assigned # of decimals in the Modbus Write AO setup.
3. The Port field in the service panel was not transmitting changes unless a static IP was used. RESOLUTION - Added the change to both Dynamic and static options.
4. Removed the Alarm Auto print tab in the Option Setup UI - this functionality has been replaced with the alarm alerts.
5. Updating V17 REF grids to display the same as V14 REF grids.

Any questions regarding this release, contact:  
[support@mcscontrols.com](mailto:support@mcscontrols.com)

---

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905  
(239)694-0089 FAX: (239)694-0031 [www.mcscontrols.com](http://www.mcscontrols.com)

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.