



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 9.20B
01/25/2013

Updates from previous versions:

Bug Fixes:

1. When the user is in the service panel and gets authorized the Accept button does not get enabled. RESOLUTION - Added a function call to the Authorization button to enable the Accept button if the entered auth level is sufficient.
2. The Edit time popup in MicroMag and V10 SW is too small and is not displaying all info. RESOLUTION - Made it larger.
3. In the Information UI the button bar was not always being hidden when switching between tabs in Graphics view or changing view to Graph or Graphics. Also, the Info Tabbed Pane was not always being disabled when switching tabs or views. RESOLUTION - Added code to hide the button bar and disable the Info Tabbed Pane when switching views or when switching tabs when multiple controllers are found.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.